



Why do Rhomberg Proximity Sensors have plastic locknuts?

All Rhomberg tubular proximity sensors from M12 to M40 are supplied with 2 black plastic locknuts. You might ask yourself – "*Why plastic? Every other brand is supplied with metal locknuts*". What most other manufacturers don't advertise is the number of faulty sensors that are returned under warranty, which are a result of the locknuts being over-tightened, causing circuit failure.

Rhomberg, many years ago identified this as a problem, and pro-actively replaced its metal locknuts with plastic. The plastic locknuts are designed to strip their threads should they be tightened beyond a reasonable torque. It is much less expensive to replace one or two plastic nuts, rather than a complete sensor, and much less upsetting when the sensor is brand new!



Plastic nuts can be ordered as spares. However, if you still prefer metal nuts, these can also be ordered as spares.

Part numbers are:

Plastic Nuts per set of 2: Aluminium Nuts per set of 2: M12-2NP, M18-2NP, M30-2NP, M40-2NP M12-2NA, M18-2NA, M30-2NA, M40-2NA



ADELAIDE/DARWIN Tel (08) 8354 0588 Fax (08) 8352 7755

SYDNEY Tel (02) 9693 9333 Fax (02) 9693 1258 **BRISBANE** Tel (07) 3391 8311 Fax (07) 3891 5603

ROCKHAMPTON Tel (07) 4921 3523 Fax (07) 4921 3013 **MELBOURNE** Tel (03) 9751 8860 Fax (03) 9751 8861

TOWNSVILLE Tel (07) 4779 1732 Fax (07) 4779 1301 **NEWCASTLE** Tel (02) 4952 3586 Fax (03) 4952 3862

WOLLONGONG Tel (02) 4271 5588 Fax (02) 4271 6377 **PERTH** Tel (08) 9446 0500 Fax (08) 9244 7466

AUCKLAND - NZ Tel +64 (09) 828 1101 Fax +64 (09) 828 1301 **QUEANBEYAN** Tel (02) 4271 5588 Fax (02) 4271 6377

CHRISTCHURCH - NZ Tel +64 (03) 365 9500 Fax +64 (03) 365 9501